MORNING SITE BRIEFING · JEDDAH · FRIDAY 20 NOVEMBER · ISSUED 06:43

Pour concrete 07-11 h; fast drying limits the rest of the day.

Rain 0 mm · 12% | Storms low | Heat 29 °C WBGT | Gusts 12 m/s

OUTDOOR LABOUR

Limited **Work/rest cycles**

07	08	09	10	11	13	14	15	16

Work/rest cycles 09-12 h, 13-17 h: at the peak, 30 min

CONCRETE POUR

Limited **Go 07-11 h, 16-17 h**

07	08	09	10	11	13	14	15	16

Limited by fast drying. Curing cover and windbreaks

ASPHALT & SURFACING

Limited **Go 08-12 h, 13-17 h**

07	08	09	10	11	13	14	15	16

Limited by rain or wet surface. Never lay or spray on a

PAINTING & COATINGS

Limited **Go 08-12 h, 13-17 h**

07	08	09	10	11	13	14	15	16

Limited by humidity or dew. Check the surface is 3 °C

CRANE LIFTS

Go **Go 07-12 h, 13-17 h**

07	08	09	10	11	13	14	15	16

No weather limits.

WORK AT HEIGHT

Go **Go 07-12 h, 13-17 h**

07	08	09	10	11	13	14	15	16

No weather limits.

EARTHWORKS

Go **Go 07-12 h, 13-17 h**

07	08	09	10	11	13	14	15	16

No weather limits.

Dust: PM2.5 up to 53 µg/m³; damp down haul roads and cutting work; masks for dusty tasks.
Dust storm risk (dust up to 219 µg/m³): goggles and masks, secure sheeting and loose materials, stop lifts if the operator loses sig

THE WEEK

Saturday 21 November	Pour concrete 07-12 h; fast drying limits the rest of the day.
Sunday 22 November	Storms possible from 14:00: do exposed work in the morning.
Monday 23 November	Pour concrete 07-12 h; fast drying limits the rest of the day.
Tuesday 24 November	Pour concrete 07-12 h; fast drying limits the rest of the day.

BRIEFING RECORD

Briefing given by _____ Date and time _____

Workers present (number) _____ Signature _____

Screening guidance from a forecast. Your contract, crane limits and site H&S plan come first.

gavacharles.github.io/kampala-heat-atlas/site-weather/jeddah

By Gava Charles · Kampala Heat Atlas · forecast data Open-Meteo