SITE WEATHER · MBARARA · FRIDAY 20 NOVEMBER

Pour concrete 08-11 h; fast drying limits the rest of the day.

Rain 0 mm · 47% | Storms low | Heat 25 °C WBGT | Gusts 10 m/s

CONCRETE POUR

Limited **Go 08-11 h**

08	09	10	11	12	14	15	16
Go	Go	Go	Limited	Limited	Limited	Limited	Limited

Limited by fast drying. Curing cover and windbreaks ready.

PAINTING & COATINGS

Limited **Go 09-13 h, 14-17 h**

08	09	10	11	12	14	15	16
Limited	Go	Go	Go	Go	Go	Go	Go

Limited by humidity or dew. Check the surface is 3 °C above dew point.

Go NO WEATHER LIMITS

Outdoor labour, Asphalt & surfacing, Crane lifts, Work at height, Earthworks.

Screening guidance from a forecast. Your contract, crane limits and site H&S plan come first.

gavacharles.github.io/kampala-heat-atlas/site-weather/mbarara

By Gava Charles · Kampala Heat Atlas · forecast data Open-Meteo

SITE WEATHER · MBARARA

The week on site

When each trade can go ahead, 08-17 h, lunch excluded

	Fri 20	Sat 21	Sun 22	Mon 23	Tue 24	Wed 25	Thu 26
Outdoor labour	all day	all day	all day	all day	all day	all day	all day
Concrete pour	08-11	none	08-11	08-10	08-10	08-11	08-11
Asphalt & surfacing	all day	none	08-11	08-10	08-10	08-11	08-10
Crane lifts	all day	08-10	08-13	08-12 15-17	08-13	all day	08-13
Work at height	all day	none	08-13	08-12	08-10	08-13	08-10
Painting & coatings	09-13 14-17	none	10-13	10-12	none	10-13	none
Earthworks	all day	none	08-13 15-17	08-13	08-10	none	08-12 14-17
Rain	0 mm 47%	6 mm 71%	1 mm 78%	4 mm 96%	11 mm 87%	4 mm 97%	2 mm 85%
Storms	low	possible	possible	likely	likely	possible	possible

go most of the day · part of the day · little or none

Times are go windows: 08-13 = from 08:00 until the lunch break; + = more windows that day.

Screening guidance from a forecast. Your contract, crane limits and site H&S plan come first.

gavacharles.github.io/kampala-heat-atlas/site-weather/mbarara

By Gava Charles · Kampala Heat Atlas · forecast data Open-Meteo

SITE WEATHER · HOW IT WORKS

How to read the cards

A daily weather check for contractors and site managers

STEP 01 · 1

The headline

The one thing to plan the day around. The key time is marked in yellow.

STEP 02 · 2

A card per trade

Problems first: Stop, Limited (go only in the hours shown), Care. Trades with no limits share one card.

STEP 03 · 3

Hour chips

8 working hours, 08:00-17:00, lunch excluded. Green go, amber care, red stop.

STEP 04 · 4

Heat uses WBGT

The standard for heat stress at work; it sets work/rest cycles.

STEP 05 · 5

Concrete and asphalt

Rain now or within three hours, wet surfaces, and drying fast enough to crack fresh concrete (ACI 305).

STEP 06 · 6

Cranes and painting

Gusts at 30 m hook height and storms; painting needs the surface 3 °C above dew point (ISO 8502-4).

STEP 07 · 7

Every day on record

Month by month against the 1991-2020 climate, for programme reviews and delay claims.

Screening guidance from a forecast. Your contract, crane limits and site H&S plan come first.

gavacharles.github.io/kampala-heat-atlas/site-weather/mbarara

By Gava Charles · Kampala Heat Atlas · forecast data Open-Meteo